



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: **04/06/2015**

Reviewed

Mine Name: Soma	Permit Number: S/023/0065	Mine Status: Suspended
Operator Name: Nephi Sandstone Corp	Inspection Date: 04/03/2015	Permit Fees: Delinquent
Inspector(s): Wayne Western	Inspection Time: 2:50 - 3:00 pm	Bond Amount: \$25,200
Attendee(s):	Weather: clear and mild	Bond Escalation: 02/25/2012
Inspection Purpose: Routine inspection		Prior Inspection: 08/14/2013

Conclusions and Recommendations

The Operator has not paid permit fees for 2015 or submitted and annual report for 2014. The site was stable and there was no sign of any recent activity.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Bond not escalated and permit fees not paid for 2015.			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There are some overhanging rocks at the face. There are tire tracks in the area where car/trucks have pulled into the mine and drive near the face.			
3.	Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC:

File: /C:/Users/WAYNEW~1/AppData/Local/Temp/acrord32_sb/A9R9ED0.tmp



Looking east



Looking east notice some overhanging rocks



Looking southeast



Looking southeast